



Aircraft Wheel & Brake
 Parker Hannifin Corporation
 1160 Center Road
 Avon, Ohio 44011

THIS DOCUMENT CONTAINS INFORMATION THAT IS CONFIDENTIAL AND PROPRIETARY TO PARKER HANNIFIN CORPORATION ("PARKER"). THIS DOCUMENT IS FURNISHED ON THE UNDERSTANDING THAT THE DOCUMENT AND THE INFORMATION IT CONTAINS WILL NOT BE COPIED OR DISCLOSED TO OTHERS EXCEPT WITH THE WRITTEN CONSENT OF PARKER, AND WILL BE RETURNED AND ALL FURTHER USE DISCONTINUED UPON REQUEST BY PARKER. COPYRIGHT PARKER. YEAR OF COPYRIGHT IS FIRST YEAR INDICATED ON THIS DOCUMENT. ALL RIGHTS RESERVED.

PARTS LIST

199-527 SEAL REPAIR KIT

60-5, 60-5C, 60-5D, 60-9, 60-10, 60-13, 60-14, 60-15A, 60-17, 60-21, 60-25, 60-25A, 60-41 PARKING VALVES

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>QUANTITY</u>
101-50353	O-Ring, 2-006-N507-90	2
101-00500	O-Ring, MS28775-010	3
101-00700	O-Ring, MS28775-012	2
CM60-5	Overhaul Instructions 60-5, 60-5A, 60-5B, 60-5C, 60-5D, 60-5E, 60-6, 60-9, 60-9B, 60-10, 60-13, 60-14, 60-15A, 60-16, 60-17, 60-21, 60-25, 60-25A, 60-41 Parking Valves	1

NOTES:

1. Elastomeric cure date required per ESP3620

199-527
 NC
 A
 B
 01-04-1983
 05-15-2000 (0339-45)
 09-30-2015 (ECO-0045265)