



NEW CLUTCH PLATES FOR HOT SHIFT P.T.O.'S.

PTO-TEC-100

TECHNICAL

DATE: November 30, 1999

TO: All Chelsea® Power Take-Off Customers

With the ever increasing and damaging effects of torsional vibration caused by today's electronic and torsionally active engines, Chelsea engineering has made a design change to the clutch plates for the 277, 271, 270, 231 and 230 series P.T.O.s.

The new improved clutch plates, which appear black in color, are able to withstand the damaging effects of torsional vibrations. Part number 378684 is obsolete and replaced with part number 379595. Part number 379595 is not interchangeable with 378684 when replacing clutch plates. Replace the complete clutch plate assembly with the newer 379595 plates. This change has also been incorporated in the appropriate service kits.

If you have any future questions please call Chelsea Technical Service at 419-866-3900.

Walt Harris
Product Manager
Chelsea Auxiliary Power Products

PTO INFO

