

8-Bolt Self-Lube Pump Obsolescence

Parker Chelsea is communicating the discontinuation of the Self-Lube Pump option for a select amount of our 8-Bolt PTOs. Due to a change within the supply chain, our lube pump options for the 880, 823, and 863 series PTOs will be obsoleted and no longer available for purchase effective immediately. Please see below the list of affected part numbers:

Affected Part Numbers
379546
329105x
329127x
329115X
329111-1X
329111-2X
329111-3X

Affected PTO Outputs
880-**LF
880-**LH
880-**LL
880-**LG
823-**LG
823-**LH
823-**LJ
863-**LG

Although the need for a self-lubricated PTO has greatly diminished in the work truck market, Parker Chelsea understands that there may be existing or future applications that will require a solution. If there is a need for an 8-Bolt Self-Lubricated PTO, please reach out to Chelsea Customer/Technical Services and we will be happy to help search for an alternative solution.

If you have questions about this bulletin or other technical questions, contact us at:

US: Chelsea Customer/Technical Services [1-888-PH4-TRUK](tel:1-888-PH4-TRUK) (1-888-744-8785)



Nick Flory
Product Manager
Chelsea Products Division
Motion Systems Group