


Gasket Revision Announcement

Effective immediately, gasket part numbers 35-P-111 and 35-P-120 are revised due to a material change from our supplier. The new gaskets are slightly thinner due to a steel inner-layer, the previous gaskets had an aluminum inner-layer. This is a running change and there will be no change to fit, form, or function.



If you have questions about this bulletin or other technical questions, please contact us at:

US: Chelsea Customer/Technical Services **1-888-PH4-TRUK** (1-888-744-8785)
Europe: Parker Hannifin Europe +49 (0) 371 3937 157

Robert Johnson
Product Manager
Chelsea Products Division
Motion Systems Group