









# TOP NEW PRODUCTS 2024




## HEAVY-DUTY - ON-HIGHWAY

| DESCRIPTION   | APPLICATION  | CROSS-REFERENCE  |
|---|--|--|
| <b>RS30345XP</b><br>Extreme Performance<br>Nano Radial Seal<br>Air Element<br><br><b>June</b> |  2022-23 International HX620 w/A26 (12.4L) Engine,<br>2017-24 International HX620 w/Cummins<br>X15 (15.0L) Engine | <b>International</b> 2515851C1<br><b>Donaldson</b> P644827<br><b>Luber-finer</b> LAF8856   |
| <b>P41000</b><br>Lube Element<br><br><b>January</b>   |  Freightliner, Western Star Trucks,<br>MCI-Motor Coach, Van Hool Buses<br>with Detroit DD13, DD15, DD16 Engines   | <b>Freightliner</b> A4711800009, A4711800209<br><b>Donaldson</b> P582506<br><b>Fleetguard</b> LF17810<br><b>Luber-finer</b> LP7184<br><b>Wix</b> WL10663 |
| <b>PF46253</b><br>Fuel Element<br><br><b>March</b>  |  DAF, Kenworth, Peterbilt Trucks;<br>Solaris Buses;<br>Cummins Engines  | <b>Cummins</b> 5335504<br><b>Freightliner</b> FF266<br><b>JLG</b> 70026453<br><b>Paccar</b> 1707078  |
| <b>PF46270 KIT</b><br>Set of 2 Fuel Filters<br><br><b>January</b>                             |  2023-24 Kenworth and Peterbilt Trucks<br>with MX-11, MX-13 Engines   | <b>Paccar</b> 2272926, 2272926PE<br><b>Donaldson</b> P583557   |

## HEAVY-DUTY - OFF-HIGHWAY

| DESCRIPTION   | APPLICATION  | CROSS-REFERENCE  |
|---|--|--|
| <b>PT23621-MPG</b><br>Maximum Performance<br>Glass Hydraulic<br>Element<br><br><b>July</b>  |  Caterpillar Compactors, Crawler Tractors, Dozers,<br>Excavators, Forestry Equipment, Loaders,<br>Motor Graders, Off-Highway Trucks, Pipelayers,<br>Pumpers, Scrapers and Wheel Tractors. | <b>Caterpillar</b> 3375270, 5715253<br><b>Donaldson</b> P580903<br><b>Fleetguard</b> HF2912<br><b>HiFi</b> SH66289<br><b>SF-Filter</b> HY90749 |
| <b>RS30350</b><br>Radial Seal Outer<br>Air Element with<br>Blank Band<br><br><b>October</b> |  60G, 60P, 75G, 85G Excavators with<br>Yanmar 4TNV98C Eng. (Final)  | <b>John Deere</b> FYD00001541<br><b>Hitachi</b> FYD00001541  |
| <b>B40166</b><br>Lube Spin-on<br><br><b>July</b>  |  Isuzu Engines  | <b>Isuzu</b> 8983758600  |
| <b>B40167</b><br>Lube Spin-on<br><br><b>April</b>   |  Bulk Lube Tanks;<br>Donaldson 1KDFF1012, P561880, P568932,<br>P568933 Bases  | <b>Donaldson</b> DBB8664<br><b>Y2K Filtration</b> P1064  |

## HEAVY-DUTY - OFF-HIGHWAY (Cont'd.)

| DESCRIPTION   | APPLICATION  | CROSS-REFERENCE   |
|---|--|---|
| <b>B40168</b><br>Lube Spin-on<br><br><b>December</b>  | John Deere 315SE, 330B, 335, 335C, 430B, 435, 437C, 485E, 486E, 488E, 653G, 670C, 670CH, 672CH, 700H, 1175, 6110L, 6210L, 6410S, 6510S Equipment | <b>John Deere</b> DZ118286  |
| <b>BF46110</b><br>Ultra High Efficiency Fuel Spin-on<br><b>March</b>  | Caterpillar Equipment  | <b>Caterpillar</b> 4227587  |
| <b>PF46249</b><br>Box-Style Fuel Element with Handle<br><b>May</b>  | John Deere Harvesters, Tractors  | <b>John Deere</b> N378886<br><b>Mann Filter</b> PU85  |
| <b>PF46253</b><br>Fuel Element<br><b>March</b>  | Dynapac CC4200 VI Roller; Hyundai HX140 Excavator; JLG 1055, 1025 Telehandlers   | <b>Cummins</b> 5335504<br><b>Freightliner</b> FF266<br><b>JLG</b> 70026453<br><b>Paccar</b> 1707078 |
| <b>PF46278</b><br>Fuel/Water Separator Element<br><b>May</b>  | Kubota Excavators, Loaders   | <b>Kubota</b> V063151880<br><b>Wix</b> WF10631  |
| <b>BF46281</b><br>High Efficiency Fuel Spin-on<br><b>March</b>  | Takeuchi Loaders   | <b>Kubota</b> K1J30143170, K1J30143172  |

## LIGHT-DUTY / MEDIUM-DUTY

| DESCRIPTION                                       | APPLICATION   | CROSS-REFERENCE  |
|---|---|--|
| <b>B40159</b><br>Lube Spin-on<br><b>March</b>     | Hyundai, Kia Automotive   | <b>Hyundai</b> 2630035505  |
| <b>B40162</b><br>Lube Spin-on<br><b>September</b> | 2020-24 Buick, 2019-25 Cadillac, 2019-25 Chevrolet, 2019-24 GMC Automotive, Light-Duty Trucks | <b>ACDelco</b> PF66<br><b>GMC</b> 12727115, 19458922, 55495105<br><b>Luber-finer</b> PH10066<br><b>Purolator</b> L11424, TL11424<br><b>Wix</b> WL10351 |
| <b>P40164</b><br>Lube Element<br><b>June</b>      | Hyundai Santa Cruz, Santa Fe, Sonata, Tucson; Kia K5, Sorento, Sportage Automotive            | <b>Hyundai</b> 263502S000<br><b>Luber-finer</b> P1086<br><b>Purolator</b> PL11752<br><b>Wix</b> WL10614  |

**⚠ WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol-A, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



800.822.5394 | baldwinfilters.com

© 2024 Baldwin Filters, a Parker Hannifin Company  
 Printed in the U.S.A.  
 Top New Products - 2024 (R 12/24)