



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit www.iecex.com

| | | |
|--|---|---|
| QAR Ref. No.: | CA/CSA/QAR15.0002/06 | Page 1 of 1 |
| QAR Free Ref. No.: | 80203901-80203902 | Status: Issued |
| Details of change: | Recertification Audit | Date of issue: 2024-05-22 |
| Location(s) audited: | Climco Coil Inc 701 Klimstra Court Morrison IL, 61270 United States of America | Valid until: 2027-06-04 |
| | Parker Hannifin Hydraulic Valve Systems 203 Pine Street Forest City NC 28043 United States of America | Audit date: 2024-04-23 |
| Issuing ExCB: | CSA - CSA Group | |
| Manufacturer: | Parker Hannifin Hydraulic Valve Systems 203 Pine Street Forest City NC 28043 | |
| Location of Manufacturer: | United States of America | |
| Product information: | Pulsar Solenoid Assemblies | |
| Type of protection: | Ex mb | |
| Related QARs: | | |
| CA/CSA/QAR15.0002/00 | CA/CSA/QAR15.0002/01 | CA/CSA/QAR15.0002/02 |
| CA/CSA/QAR15.0002/03 | CA/CSA/QAR15.0002/04 | CA/CSA/QAR15.0002/05 |
| Related Certificates (manual insertion): | | |
| IECEX SIR 15.0023X | | |
| Related Certificates (automatic linking): | | |
| Related Certificates for previous versions: | | |
| IECEX SIR 15.0023X issue: 0 | IECEX SIR 15.0023X issue: 1 | IECEX SIR 15.0023X issue: 2 |
| IECEX SIR 15.0023X issue: 3 | | |
| Comments: | | |